

TECHNICAL BULLETIN

SU-95-4 31 March 1995 Revision B, 21 April 2015

MODEL AFFECTED: UH-1H

SUBJECT: ALTERNATE SPARE PART; SWASHPLATE AND

SUPPORT ASSEMBLY P/N 204-011-400-129

HELICOPTERS AFFECTED: UH-1H helicopters which are non-type certificated

and owned and operated by other than an Armed

Service of the United States.

COMPLIANCE: Upon receipt. Refer to ASB UH-1H-15-12 for

additional compliance requirements.

DESCRIPTION:

Revision B supersedes and replaces all previous issues of Special Use (SU) Technical Bulletin (TB) SU-95-4.

Review of UH-1H fatigue and flight spectrum data has determined the P/N 204-011-400-129 Swashplate and Support Assembly is **not usable** on the UH-1H due to the differences in the individual detail component retirement lives.

This technical bulletin is cancelled and the previous authorization to use the -129 assembly is rescinded. Operators of UH-1H helicopters, as described in the **HELICOPTERS AFFECTED** block above, who have installed the P/N 204-011-400 -129 Swashplate and Support Assembly under authority of previous issues of this technical bulletin, should refer to ASB UH-1H-15-12 for information on how to reconfigure their assemblies for continued operation.

APPROVAL:

Bell Helicopter does not authorize use of this bulletin to obtain approval from any civil regulatory authority for installation of P/N 204-011-400-129 Swashplate and Support Assembly on any type certificated UH-1 helicopter.

TB SU-95-4B
Page 1 of 2
No Technical Data
Approved for Public release

The engineering design aspects of this bulletin are Bell Helicopter Engineering approved.

CONTACT INFO:

For any questions regarding this bulletin, please contact:

Bell Helicopter Product Support Engineering - Medium Military Helicopters
Tel: 817-280-3548 / mts-medium@bh.com

MANPOWER:

Approximately 0.25 man-hour is required to complete this bulletin. This estimate is based on hands-on time, and may vary with personnel and facilities available.

WARRANTY:

There is no warranty credit applicable for parts or labor associated with this bulletin.

MATERIAL:

None required.

SPECIAL TOOLS:

None required.

WEIGHT AND BALANCE:

Not affected.

ELECTRICAL LOAD DATA:

Not affected.

REFERENCES:

Alert Service Bulletin UH-1H-15-12

PUBLICATIONS AFFECTED:

Technical Bulletin SU-95-4 Rev A

ACCOMPLISHMENT INSTRUCTIONS:

None.

TB SU-95-4B
Page 2 of 2
No Technical Data
Approved for Public release